

marantz

SERVICE BULLETIN

SS-MAR0234

model number 140	bulletin number M-140-3
for serial numbers SEE BELOW	
subject PROTECTION RELAY REPLACEMENT	
engineering approval [Signature]	date 5-14-76

If you receive customer complaints concerning malfunction of the Speaker Protection Relay (LN01) in the Marantz Model 140 and replacement is required, it is recommended that LN01 be replaced with an improved twin contact relay part number LY2-0240-090.

This improved relay has been incorporated into units with serial number 102001 (USA); 600501 (Canada); 500901 (Europe) and later.

Almeida

Albert Almeida, Manager
Technical Services