

 SERVICE BULLETIN	model number 2216	bulletin number M-2216-1
	for serial numbers ALL	
	subject SERVICE MANUAL CORRECTION	
	technical services approval <i>B. Coffey</i>	writer <i>SKJ</i>
engineering approval <i>3/1/77 Steward. E. Leggett</i>	date 7-7-77	

OBJECTIVE

This bulletin is issued to inform you of an omission in the Marantz Model 2216 Service Manual.

APPLICATION

Incorporate this addition into your manual as soon as possible to ensure correct service information.

PROCEDURE

Refer to the Service Manual, Page 24, Parts List and locate Ref. Desig. H714. Directly below it add this information:

<u>Ref. Desig.</u>	<u>QTY. U C E</u>	<u>Part Number</u>	<u>Description</u>
H715	1 1 1	HD2-0005-010	Diode W - 06 - B
H716	1 1 1	HD2-0005-010	Diode W - 06 - B
H717	1 1 1	HD2-0005-010	Diode W - 06 - B
H718	1 1 1	HD2-0005-010	Diode W - 06 - B